Maryland Historical Trust

Maryland Inventory of Historic Properties number:	1755
Name: \(\square \)	ver Consil
The bridge referenced herein was inventoried by the Ma Historic Bridge Inventory, and SHA provided the Trust The Trust accepted the Historic Bridge Inventory on Ap determination of eligibility.	with eligibility determinations in February 2001.
MARYLAND HIST	
Eligibility RecommendedX	Eligibility Not Recommended
MARYLAND HIST Eligibility RecommendedX Criteria:AB \(\sum_C \) Considerations	Eligibility Not Recommended
Eligibility RecommendedX	Eligibility Not Recommended
Eligibility RecommendedX Criteria:AB \(\sum_C \) Considerations	Eligibility Not Recommended
Eligibility RecommendedX Criteria:AB \(\sum_C \) Considerations Comments:	Eligibility Not Recommended EABCDEFGNone
Eligibility RecommendedX Criteria:AB \(\sum_C \) Considerations	Eligibility Not Recommended EABCDEFGNone

de, O

MHT Number PG:71-38

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust

Name and SHA No. 16017 over Conrail

Location: Street/Road Name and Number: Maryland Route 450 over Conrail
City/Town: Bowie Vicinity
County: Prince George's
Ownership: X State County Municipal Other
This bridge projects over:Road_X_RailwayWaterLand
Is the bridge located within a designated district: yes X no
NR listed districtNR determined eligible districtlocally designatedother Name of District
Bridge Type:
Timber BridgeBeam BridgeTruss-CoveredTrestleTimber-and-Concrete
Stone Arch
Metal Truss
Movable BridgeSwingBascule Single Leaf_Bascule Multiple LeafVertical Lift_Retractile_Pontoon
Metal GirderRolled GirderRolled Girder Concrete EncasedPlate Girder _X_Plate Girder Concrete Encased
Metal Suspension
Metal Arch

Metal Cantilever
X Concrete Concrete ArchConcrete Slab_X Concrete BeamRigid FrameOther Type Name

Description:

Describe Setting:

Bridge No. 16017 carries traffic east-west on Maryland Route 450 over Conrail Railroad. The bridge carries traffic over two sets of railroad tracks. The east track is in poor condition and has not been used recently. The west approach roadway is curved and sight distance is limited. Multiple overhead utility lines are visible paralleling the bridge. Commercial buildings are visible on the West side of the bridge. The areas on both sides of the bridge are covered in light forrest growth, approximately 30-50 years old.

Describe Superstructure and Substructure:

Bridge No. 16017 is a three span bridge consisting of two 31'6" cast in place reinforced concrete T-beam spans, and one 45' concrete encased thru plate girder span. The floor system consists of a 24'0" roadway and two 6" curbs of reinforced concrete. This bridge was built by Maryland State Roads Commission in 1926. The parapets are solid cast reinforced concrete. The east abutment is a cast in place reinforced concrete spill-thru abutments on spread footings set 18'± below bridge seat. The west abutment is a cast in place reinforced concrete stub type on spread footings set 4'± below bridge seat. The Intermediate supports consist of two cast in place reinforced concrete 3 column piers on spread footings set 28'± below bridge seat.

A 1988 inspection report indicates that both backwalls had horizontal cracking and surface spall. The west abutment face had a 1/4" open vertical crack under beam three, pier columns had random vertical cracking and pier caps have horizontal cracking with efflorescence, and rebar was exposed in the floor beams of span two.

Discuss Major Alterations:

Details of repairs to the structure are scanty. In 1992, 30% of the deck was patched. In 1993 undermined areas of the west abutment were filled, and bituminous curbing was installed on the northwest slope to direct rainwater from the west abutment. The different abutment types indicates that one of the abutments was replaced and may represent an episode of major alteration.

In the future a new bridge will be built as part of the Maryland Route 450 relocation project at a new location over Conrail, however the old bridge (16017) is to remain in service.

PG: 71A-58

History:

When Built: 1926

Why Built: Local transportation needs

Who Built: Maryland State Roads Commission, W.C. Hopkins

Why Altered: Not applicable

Was this bridge built as part of an organized bridge building campaign: Yes

Surveyor Analysis:

This bridge may have NR significance for association with:

_A Events __Person

X C Engineering/Architectural

Was this bridge constructed in response to significant events in Maryland or local history:

It is unknown whether this bridge was constructed in response to significant events in Maryland or local history.

In 1968 the railroad tracks now owned by Conrail were owned by Pennsylvania Central. There may be a stone cobble wingwall in existence under the west abutment. This may be a form of erosion control or it may be a portion of an older bridge in the same location.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

It is unknown whether the construction and/or alteration of this bridge has had significant impact on the growth and development of the area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district?

No, this bridge does not appear to be located in an area which may be eligible for historic designation.

Is the bridge a significant example of its type?

This bridge may be a significant example of its type.

Does the bridge retain integrity of the important elements described in the Context Addendum?

Yes, this bridge appears to retain the integrity of most of its character defining elements. One of its abutments may have been replaced however, the concrete parapets the bridge deck, and a plaque indicating the year of construction indicates that most of this bridge appears to retain integrity.

PG: M/A-38

Should this bridge be given further study before significance analysis is made and Why?

Further research of this bridge is unnecessary. This bridge is eligible for inclusion on the National Register of Historic Places.

Bibliography:

Greiner, Inc.

1995 Maryland Inventory of Historic Bridges.

Spero, P.A.C. & Company, and Louis Berger & Associates

1994 Historic Bridges in Maryland: Historic Bridge Context.

State Highway Administration

v.d. Bridge Inspection Files.


United States Geological Survey

1965 7.5' Lanham Quadrangle, photorevised 1979.

Surveyor:

Name: Jason D. Moser Date: September 1995

Organization: State Highway Admin. Telephone: (410) 321-2213 Address: 2323 West Joppa Road Brooklandville, MD 21022





Inventory	#	F6:	71-38
<i>a</i>			

Name 16017 - MD 450 OVER COWRAIL County/State PRINCE GEORGES COUNTY/M Name of Photographer WALLY KING Date 196	(.
Location of Negative SHA	_
Description EAST APPROACH LOOKING WEST	_
Number $\frac{\cancel{9} \text{ of } \cancel{\cancel{4}}\cancel{\cancel{5}}}{\cancel{5}}$	

The Mark of USO Moory



Inventory # PG: 71-38

Name 16017- MO 450 OVER CONRAIL
County/State PRINCE GEURGES COUNTY MY
Name of Photographer WALLY KING
Date \\qs
Location of Negative SHA
Description WEST APPROACH LOOKING EAST
Number 82 of 23



Inventory # <u>PG:71-38</u>
Name 16017- MD 450 OVER CONRAIL County/State PRINCE GREAGES COUNTY Name of Photographer WALLY KING Date 195
Location of Negative SHA
Description PLAQUE - "COLLINGTON BYUNGE"

Number 10 of 25 5

990KNOOM[03]050 4611 H



Inventory # <u>PG:71-38</u>

Name 16 017 - MP 450 ONER CONRAIL County/State PRINCE GEORGES COUNTY Name of Photographer WALLY KING Date 1 95
Location of Negative SHA
Description SOUTH ELEVATION
Number 4 of 255

THE PROOMED STORMS ASSET



Inventory # P6171-38

Name 16017 - MD 450 OVER CONRAIL
County/State PRINCE GEORGES COUNTY/M
Name of Photographer WALLY KING
Date 195
*
Location of NegativeSHA
A-1 - 1 - 1 - 1
Description NORTH ELEVATION
51 000
Number 200 of 285